RECORD OF FATAL AND SERIOUS ACCIDENTS.

[MINING.]

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
ith January ...	2	The Mysore Gold Mine, Bowringpet Taluk, Kolar District.	16	9	...	1 B. Chinna Venkatappah.	23
8th January ...	12	Do ...	8	1	...	1 Hajee Abdulla ...	58
18th January ...	5	Do ...	15	8	...	1 T. Kuppuswamy	30
20th January ...	6	Do ...	13-30	6½	...	1 B. Abboy ...	36
21st January ...	17	Do ...	19-30	4½	...	1 C. Manickam ...	23
3th February ...	25	Do ...	8-40	1⅔	...	1 S. Murugan ...	30
12th February ...	29	Do ...	17-30	2½	..	1 K. Singaram ...	28
26th February ...	36	Do ...	11	4	...	1 A. Chengaiyan ...	28
2nd March ...	37	Do ...	13	6	...	1 C. Ganga Reddy	30
3rd March ...	40	Do ...	18-30	3½	...	1 T. Muniswamy ...	28
5th March ...	41	Do ...	10	3	1 K. Chinnaiyan...	...	38

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937. Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Concreting cooly	Drive (Intermediate), 49th level S., McTaggart's Main Winze	XIX	While handing up a granite stone, he overbalanced and fell, and the stone dropped on his legs.	Fracture of lower 3rd of right thigh and both bones of left leg.
Sawyer ...	Saw mill, Carpenters' Shop. (surface.)	XX	While feeding a piece of timber, his hand slipped and came in contact with the revolving saw.	Left thumb and left index finger crushed and amputated.
Blackrock cooly	Stope below the 43rd level N., McTaggart's Vertical Shaft.	XIX	While lifting a stone it broke and a piece fell on his knee.	Wound of left knee, joint opened.
Packwall cooly ...	Stope below the 42nd level N., Mc Taggarts' Vertical Shaft.	XIX	While breaking a piece of rock, a chip flew off and struck his knee.	Wound of left knee, joint opened.
Stuff cooly ...	Drive, 59th level N., Air Shaft.	XVII	While re-railing a bandy his hand was caught between it and a side of the level.	Middle and ring fingers crushed and amputated at the metacarpophalangeal joint.
Handjumper cooly.	Stope below the 51st level N. (East Reef), Edgar's Shaft.	XIX	While clearing stuff, a piece of rock fell on his arm.	Lacerated wound of left forearm, extensor tendons to index, middle and ring finger cut.
Stuff cooly ...	Drive, 890 ft. level S., Rowse's Shaft.	XIX	While filling a bandy at a chute, a piece of rock fell on his knee.	Traumatic arthrotomy of left knee joint.
Stuff cooly ...	No. 1 winze below the 80th level N., Edgar's Sub-Vertical Shaft.	XV	While riding up in a bucket, he fell away and was caught on a divider.	Wounds of scalp, face, over left clavicle with fracture of 2nd and 3rd ribs with surgical emphysema and wounds of left leg.
Handjumper cooly.	No. 47 stope below the 2,670 ft. level N., Tennant's Shaft.	XIX	While starting a hole, a piece of rock fell on his knee.	Wound of right knee, joint opened.
Stuff maistri (M. 14, 482.)	Skiproad below the 466 ft. level, Plummer's Shaft.	XIX	While clearing a choke, a piece of timber fell on his leg.	Simple fracture, both bones of lower 3rd of left leg, contused abrasions of back and lower 3rd of left leg.
Concreting cooly	Stope above the 51st level S., Ribblesdale's Main Winze.	XIX	Collapse of packwall	Compound fracture of both bones of right leg, simple fracture of both bones of right fore-arm and crushed fingers, fracture of base of skull and internal laceration of lungs.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
5th March ...	56	The Mysore Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	23	8	...	1 K. Govindan ...	20
9th March ...	47	Do ...	13	6	...	1 P. Ponnan ...	35
20th March ...	51	Do ...	3-30	4½	...	1 M. Manickam ...	30
25th March ...	60	Do ...	23-30	4½	...	1 K. Munian ...	44
26th March ...	80	Do ...	12	5	...	1 P. Dhanapal ...	26
19th April ...	76	Do ...	14	7	...	1 M. Nagan ...	27
26th April ...	82	Do ...	9	2	...	1 O. Muniswami ...	33
26th April ...	86	Do ...	13-30	6½	...	1 B. Poongavanam	32
18th May ...	104	Do ...	12-30	5½	...	1 S. Gopal ...	25
16th June ...	118	Do ...	7-45	¾	...	1 S. David ...	37
16th June ...	125	Do ...	19-30	4½	...	1 A. Armugam ...	31
1st July ...	138	Do ...	9-30	2½	...	1 B. Venkatappa ...	40

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Machine cooly ...	Sink of No. 1 winze in No. 3 drive S., 2,760 ft. level, McTaggart's Incline Shaft.	XVIII	Struck by a bucket which was lowered uncontrolled.	Contused swelling of lower part of back. (Lumbo sacral region.)
Handjumper maistri (M. 10,670.)	No. 22 stope above the 1,620 ft. level N., Gilbert's Shaft.	XV	While drilling a hole, a jumper dropped on his knee.	Wound of left knee, joint opened.
Machine cooly ...	Drive, 83rd level N., Edgar's Sub-Vertical Shaft.	XIX	While watering a hole, some slush fell in his eye.	Traumatic conjunctivitis of right eye with a central corneal ulcer.
Machine maistri (M. 10,063.)	Sink of No. 1 winze below the 2,760 ft. level, No. 3 drive S., McTaggart's Incline Shaft.	XVIII	Struck by a loaded bucket which ran down uncontrolled to the sink.	Contusion of lower part of back, wound of scalp, contused abrasion dorsum of right foot.
Machine cooly ...	Plat, 88th level, Edgar's Sub-Vertical Shaft.	XIX	While drilling a hole, a piece of rock fell on his hand.	Tetanus (probably due to a neglected wound on his hand.)
Handjumper maistri (M. 14,946.)	No. 86 stope below the 31st level S., Ribblesdale's Shaft.	XIX	While examining the working face for loose, a chip of rock flew into his eye.	One day old penetrating wound with traumatic cataract in right eye.
Handjumper maistri (M.B. 12,786)	No. 17 stope above the 1,350 ft. level S., Gilbert's Shaft.	XIX	While barring down loose, a chip of rock flew into his eye.	Wound of left cornea.
Unloading cooly	Plat, 51st level, Edgar's Shaft.	XVII	While pushing a bandy, he slipped and fell.	Two days old colles' fracture left.
Timber cooly ...	Intermediate drive above the 44th level N., McTaggart's Vertical Shaft.	XIX	While fixing a timber, a piece of rock fell on his leg.	One day old wound of left tendo-achilles, tendon partly cut.
Timber cooly ...	Plat, 400 ft. level, Crocker's Shaft.	XVI	While unloading tools from the bandy, it was suddenly hoisted, with the result that he was caught under it.	Extensive lacerated wound of scalp, wounds of both knees, and contused swelling lumbothoracic region of back.
Machine cooly ...	Winze in fold below 1,180 ft. level N., McTaggart's Incline Shaft.	XIX	While clearing stuff, a piece of rock fell on his hand.	Lacerated wound dorsum of right hand with extensor tendon cut.
Handjumper maistri (M. 13,044).	No. 17 Stope above the 1,350 ft. level S., Gilbert's Shaft.	XIX	While barring down loose, a piece of rock fell on his foot.	Lacerated wound dorsum of right foot, extensor tendon slightly injured.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
7th July ...	132	The Mysore Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	11-30	4½	...	1 A. Ponnurangam.	22
7th July ...	133	Do ...	18-30	3½	...	1 Y. Lakshmiah ...	20
8th July ...	135	Do ...	7-45	¾	...	1 V. Moses ...	25
14th July ...	140	Do ...	14-45	7¾	1 K. Muthuswami.	...	42
						1 K. Ramaswami ...	26
21st July ...	150	Do ...	10-30	3½	...	1 B. Jayanathan ...	23
1st August ...	153	Do ...	14-30	7½	...	1 K. Samuel ...	26
3rd August ...	155	Do ...	11	4	1 Manickam ...	...	40

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Concreting cooly.	Cage-road, 20 ft. below the 51st level, Ribblesdale's No. 2 Auxiliary Shaft.	XIX	While building a packwall, a granite stone fell on his leg.	Lacerated wound, lower 3rd of left leg, extensor muscles, tendons and blood vessels cut.
Machine cooly ...	No. 2 crosscut west, 88th level, Edgar's Sub-Vertical Shaft.	XIX	While drilling a hole, a piece of rock fell on his leg.	Wound lower 3rd of left leg, tendo achilles partly cut.
Loco-driver ...	Plat, 32nd level, Edgar's Shaft.	XVII	His foot was caught between the wheels of a locomotive and a sand bin.	Extensive lacerated wound dorsum of right foot and ankle with gross loss of tissue and compound fracture of tarsals and metatarsals
Handjumper cooly.	Stope below the 2,790 ft. level S., Tennant's Shaft.	XIII	Due to deepening a socket containing a remnant of the previous charge of explosives.	Peppered and lacerated wounds all over the body, multiple compound comminuted fractures of left foot with extensive tissue loss, compound comminuted fracture of right little finger, wounds and foreign bodies in both eyes and compound fracture of left ulna (leg and finger amputated) Died in hospital on 15th July.
Do ...	Do ...	Do	Do ...	Peppered wounds all over the body, foreign bodies in both eyes, with penetrating wound and hæmorrhage into the anterior chamber.
Blackrock cooly.	No. 39 Stope below 3,226 ft. level (Intermediate) S., McTaggart's Incline Shaft.	XIX	While building a packwall, a piece of rock fell on his knee.	Wound of right knee, joint opened, quadriceps tendon cut.
Blackrock cooly.	No. 29 Stope below the 49th level, Ribblesdale's Auxiliary Main Winze.	XIX	While breaking a piece of rock, a chip flew into his eye.	Penetrating wound of left eye with prolapse of iris.
Cyanide cooly ...	Extractor Room, Cyanide Department (Surface).	XXIII	He was struck by the handle of a trolley he was pulling.	Contusion of abdominal wall. Died in hospital on 8th August.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed *(All males unless otherwise stated)*	Names and Number of Persons injured *(All males unless otherwise stated)*	Reputed Age
6th August ...	157	Mysore Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	7–50	8-5/6	...	2 C. Lakshmiah ...	35
						M. Mammy ...	40
10th August ...	159	Do ...	10	3	...	1 Iyloo Naidu ...	50
24th August ...	171	Do ...	12-45	5¾	...	1 R. Periaswami ...	31
31st August ...	172	Do ...	12	5	...	1 Subban *alias* Subbadu.	29
24th September ...	179	Do ...	2	3	...	1 V. Muniswami ...	42
28th September...	180	Do ...	13	6	...	1 A. Kalavarayan.	32
6th October ...	188	Do ...	12-30	5½	...	1 M. Papoo Reddy.	51
13th October ...	189	Do ...	19	4	1 E. Govindan ...	...	35
28th October ...	200	Do ...	10-30	3½	...	2 A. Ponnuswami.	40

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Timber maistri (M. 13,483 B. 8,829).	Drive, 33rd level S., South Reclamation Winze.	XI	A rockburst ...	Wounds of scalp with fracture of base of skull, and potts' fracture left.
Machine cooly ...	Do ...	Do	Do ...	Wound of scalp, right forearm, dorsum of hand, right knee, leg and contusion of back.
Mill cooly ...	Stamp Mill, Surface	XXIII	While raising a guide timber, his arm was caught between it and a king post.	Lacerated wounds of lower 3rd of left forearm with comminuted fracture of radius.
Handjumper cooly	Stope below the 43rd level, N., Ribblesdale's Auxiliary Main Winze.	XI	A rockburst ...	Fractures of 1st and 2nd right transverse process, compression fracture of right half of 2nd lumbar body, wounds of left fore-arm, index and middle fingers and knee.
Handjumper cooly	Stope below the 28th level N., McTaggart's Incline Shaft.	XIX	Whilst cleaning down stuff, he slipped and fell on the working face.	Wound of right palm with comminuted fracture of proximal phalanx of index finger and colles' fracture, left.
Machine maistri (M. 10,809—B. 7,369).	Stope above the 51st level (E. Reef) S., No. 1 Incline.	XIX	While barring down loose, a chip of rock flew into his eye.	Corneal ulcer of left eye (central) due to 4 days' old wound.
Stuff cooly ...	Drive, 2,120 ft. level N., Tennant's Shaft.	XIX	While filling a bandy at a chute, a piece of rock fell on his knee.	Wound of left knee, joint opened.
Handjumper cooly.	Stope below the 2,890 ft. level N., Tennant's Main Winze.	XIX	while cleaning down stuff, he slipped and fell.	Posterior dislocation of right hip joint.
Blaster (M. 13,307 —B.8,768).	No. 9 Stope above the 450 ft. level N., McTaggart's Incline Shaft.	XIV	While igniting a round of holes, he was caught in the blast.	Fracture of head and severe wounds all over the body. Died on the way to hospital.
Handjumper maistri (M. 10,354.)	No. 140 Stope above the 47th level N., Ribblesdale's No. 2. Auxiliary Shaft.	XIII	Due to the deepening of a socket containing a remnant of the previous charge of explosives.	Penetrating wound of left eye with prolapse of iris and hæmorrhage into the anterior chamber, wounds of right eye, scorched and lacerated wounds of right forearm and left hand.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
		Mysore Gold Mine, Bowringpet Taluk, Kolar District—*concld.*				Thimmarayadu...	35
15th November ...	206	Do ...	13	4	2 V. Ebenezàr ...	...	18
					K. Manickam ...	...	30
24th November ...	208	Do ...	6-30	7½	...	1 A. Chowdappa ...	28
3rd December ...	212	Do ...	10	3	...	1 V. Narayanan ...	36
26th December ...	219	Do ...	21-45	6¾	1 R. Krishtan ...	...	25
2nd January ...	1	The Champion Reef Gold Mine, Bowringpet Taluk, Kolar District.	18-45	3¾	...	1 Kolandayappan...	25
11th January ...	7	Do. ...	14	7	...	1 Duraiswami ...	35
12th January ...	8	Do ...	10-45	3¾	...	1 Yellan ...	29
16th January ...	11	Do ...	3-30	4½	...	1 Rangappah ...	35
19th January ...	13	Do ...	11	4	...	1 Joseph ...	22

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Handjumper cooly.	No. 140 Stope above the 47th level N., Ribblesdale's No. 2 Auxiliary Shaft.	XIII	Due to the deepening of a socket containing a remnant of the previous charge of explosives.	Penetrating wound of left eye with hæmorrhage into the anterior chamber, wounds and foreign bodies in right eye.
Timber cooly ...	Dump above the 48th level, Ribblesdale's Auxiliary Main Winze.	XI	A rockburst ...	Fracture of base of skull with deep wound above left ear and wounds all over the body.
Timber maistri (M. 12,780).	Do	Do	Do ...	Wounds of scalp, fracture of sacrum and pelvis. Died in hospital the same day.
Jackhammer cooly.	Stope above the 1,060 ft. level N., Rowse's Shaft.	XIX	While drilling a hole, some pieces of rock fell on him.	Wounds of left outer ankle, lower 3rd of right leg, tendo-achilles partly cut.
Head maistri (M. 11,572).	Stope below 2,440 ft. level N., Tennant's Shaft.	XIX	While breaking a piece of rock, a chip flew into his eye.	Penetrating wound of left eye with slight prolapse of iris.
Stuff cooly ...	No. 1 winze below 84th level S., Edgar's Sub-Vertical Shaft.	XV	He fell down the winze for a distance of about 200 ft.	Fracture of skull and left upper arm and multiple wounds all over the body.
Concreting cooly	Stope above the 73rd level, S., North Main Winze.	XI	A burst of quartz ...	Deep laceration of both sides of right ankle, tendo-achilles lacerated and ankle joint opened.
Stuff cooly ...	Drive, 23rd level, S., Tennant's Shaft.	XVII	While tramming a quartz bandy, he slipped and fell against the foot-wall.	Wound of scalp, right shoulder, right knee, dorsum of foot, contused abrasions of back and rupture of right tympanum.
Stuff cooly ...	Stope above the 75th level, South Development Winze.	XIX	While cleaning down stuff, a piece of rock fell on his foot.	Wound of left inner ankle with synovitis of left ankle joint.
Stuff cooly ...	Drive, 78th level N., North Main Winze.	XIX	While filling a bandy at a chute, a piece of rock fell on his arm.	Wound lower 3rd of left fore-arm, muscles cut.
Timber cooly ...	Foot wall drive, 80th level S., South Development Winze.	XIX	Being scared by a rockburst he ran for safety when he slipped and fell.	Wound dorsum of right foot and contusion of left wrist.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
21st January ...	9	The Champion Reef Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	19	4	...	2 Rajoo ... and Nallathambi ...	22 22
27th January ..	18	Do ...	12-40	5⅔	...	1 W. Rajoo ...	28
27th January ...	14	Do ...	21-30	6½	...	1 Muniswami ...	35
1st February ...	28	Do ...	19-30	4½	...	1 Latchmanan ...	42
3rd February ...	23	Do ...	17	2	1 B. Krishtan ...	...	27
4th February ...	24	Do ...	15	8	1 T. Perumall ...	...	23
8th February ...	26	Do ...	12-30	5½	...	2 Chinnaswami and Chinnappan ...	22 28
16th February ...	32	Do ...	20	5	1 Jyavoo ...	...	40

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Timber cooly ...	Rill stope above the 74th level N., No Main Winze.	XI	A burst of quartz ...	Extensive lacerated wound of right axilla, muscles cut.
Do ...	Do ...	Do	Do ...	Contused abrasions of back and contused swelling dorsum of left foot and abrasion of right leg.
Machine cooly ...	Stope above the 78th level S., North Main Winze.	XIX	While drilling a hole, a piece of rock fell on his foot.	Wound dorsum of right foot.
Machine cooly ...	Sink, 100 feet below 51st level, Gifford's Shaft.	XIX	While mixing concrete, a piece of rock fell on his foot.	Extensive penetrating wound right through right foot, compound fracture 3rd, 4th and 5th metatarsals and destruction of soft tissues.
Machine cooly ...	Rise for headgear above the 76th level N., North Main Winze.	XIX	While drilling a hole, a piece of rock fell on his leg.	Extensive lacerated wounds lower 3rd of right leg with muscles injured.
Concreting cooly	Capstan road above the 28th level, Tennant's Shaft.	VIII	While working in the shaft, he fell down a distance of 120 feet.	Wounds of scalp with fracture of skull and base of skull, fractures of left clavicle, humerus, 4 or 5 ribs and fracture of right fore-arm and left thigh. Died in hospital the same day.
Machine cooly ..	Ladderway in No. 1 winze below the 80th level S., South Development Winze.	XV	While climbing up by ladder, he somehow slipped and fell away.	Multiple wounds all over the body.
Packwall cooly ...	Stope above the 75th level N., South Development Winze.	XI	A burst of quartz ...	Wound of left knee, joint opened.
Do ...	Do ...	Do	Do ...	Compound comminuted fracture into left knee joint with extensive lacerated wound of leg.
Machine maistri (M. 13, 862, B. 8, 995).	No. 1. winze below the 80th level S., South Development Winze	XV	While riding up in the bucket in a winze, he somehow overbalanced and fell to the bottom.	Head smashed and right leg broken below the knee and wounds all over the body.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed *(All males unless otherwise stated)*	Names and Number of Persons injured *(All males unless otherwise stated)*	Reputed Age
18th February ...	33	The Champion Reef Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	1-0	2	...	1 Chowdappa ...	25
19th February ...	43	Do ...	2-30	3½	...	1 Arokiaswami ...	23
6th March ...	50	Do ...	5	6	...	1 M. Muniswami ...	45
6th March ...	44	Do ...	10-50	3 5/6	...	2 Perumal ...	30
						and	
						Ramachandra Reddy.	35
7th March ...	53	Do ...	4	5	...	1 R. Muniswamy	24
14th March ...	54	Do ...	11-30	4½	...	1 Jaganatham ...	25
15th March ...	55	Do ...	21-30	6½	...	1 Yegambaram ...	26

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Machine cooly ...	Rise for rope race above the 55th level, Gifford's Shaft.	XIX	While climbing up by ladder, a piece of rock fell on his leg.	Left tendo-achilles completely cut.
Stuff cooly ...	Drive, 78th level S., South Development Winze.	XI	A burst of rock ...	Wounds and contused abrasions of back, wound upper 3rd of right arm, lower 3rd of right thigh, middle of right leg, dorsum of foot, left knee, lacerated wound lower 3rd of left forearm, wrist, contused wounds and abrasions of right knee.
Concreting maistri (M. 10, 313).	No. 3, winze below 80th level S., South Development Winze.	XIX	While aligning a concrete former, some dust fell into his eye.	Traumatic conjunctivitis of left eye.
Machine cooly ...	Cross cut W. 80th level, Heathcote Shaft.	XI	A rockburst ...	Simple fracture of upper 3rd of left forearm, wounds of face, both forearms and legs.
Do ...	Do ...	Do	Do	Lacerated wounds of scalp, right shoulder, forearm left elbow, right leg, dorsum of foot with extensor tendons cut.
Machine cooly ...	Sink, 230 feet below the 61st level, Gifford's Shaft.	X	While at work in the sink, a plank fell on his hand.	Lacerated wound of palm and dorsum of right hand with compound fracture of last metacarpal.
Timber cooly ...	Stope above the 78th level N., North Main Winze.	XI	A rockburst ...	Wounds of scalp, left eye-brow, right elbow, forearm, knee, dorsum of foot, wounds of lower 3rd of left leg with tendo-achilles slightly injured, contused abrasions lower part of back and contusion of left inner ankle. Fracture of left internal malleolus, compression fracture of 1st lumbar vertebra.
Stuff cooly ...	Drive, 78th level S., North Main Winze.	XVII	Run over by a bandy ...	Wound of right great and 2nd toes, great toe nail off and impacted fracture of neck of right femur.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
7th April ...	68	The Champion Reef Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	18-30	3½	1 Perumal ...	...	35
						1 Iyavoo ...	30
9th April ..	70	Do	3-30	4½	...	1 Anthony Cruz ...	25
10th April ...	79	Do ...	20	5	...	1 V. Rangaswamy	25
17th April ...	89	Do ...	2-30	3½	...	1 Muniswami ...	40
18th April ...	75	Do ...	11	4	1 Dharman ...	...	30
24th April ...	90	Do ...	6	7	...	1 Krishnan ...	30
27th April ...	84	Do ...	13-40	6⅔	...	1 Vadivelu ...	25
29th April ...	91	Do ...	11	4	...	1 Chinnakannoo ...	33
2nd May ...	92	Do ...	20	5	...	1 Dhanapal ...	21
6th May ...	93	Do ...	6	7	...	1 Annamalai ...	35

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Concreting maistri (M. 13,182)	Stope above the 76th level S., North Main Winze.	XI	A rockburst ..	Multiple wounds all over the body and fracture of spine at the middle and deep wound of left chin.
Concreting cooly.	Do ...	Do	Do ..	Multiple wounds of both lower extremities and wounds lower third of back and left eye-brow.
Winch driver (D 396).	Drive, 80th level S., South Development Winze.	XIX	While walking along the level, he tripped against a sleeper and fell.	Lacerated wound of left knee, joint opened.
Machine cooly ...	Rise above the 28th level S., Tennant's Shaft.	XIX	While drilling a hole, the jumper broke and fell on his finger.	Lacerated wound of left last finger with compound fracture of middle phalanx.
Door boy ...	Drive, 72nd level N., North Main Winze.	XVII	Run over by a bandy ...	Lacerated wound sole of right foot and contused abrasions dorsum of foot with fractures of 4th and 5th metatarsals.
Machine cooly ...	Drive, 74th level N., North Main Winze.	XI	A rockburst ...	Wounds of scalp with fracture of skull and multiple wounds all over the body. Died in hospital the same day.
Machine maistri (M. 14545/B.—9260).	Sink 50 feet below the 55th level, Gifford's Shaft.	XIX	While drilling a hole, the jumper broke and the machine fell on his toes.	Lacerated wounds of left great and 2nd toes.
Stuff cooly ...	Drive, 78th level S., South Development Winze.	XIX	While pushing a bandy along the level, his foot slipped between two planks causing his knee to strike against the rail.	Lacerated wound of right knee, joint opened.
Stuff cooly ...	Plat, 65th level, Gifford's Shaft.	XIX	The bucket he was about to tip descended on him.	Potts' fracture right.
Timber cooly ...	Rill Stope above the 74th level S., South Development Winze.	XI	A rockburst ...	Simple fracture of upper 3rd of right arm, wounds of elbow, compound fracture of upper 3rd of forearm, wounds of scalp, and left forearm.
Machine cooly ...	Sink of No. 2 Winze 170 feet below the 80th level N., South Development Winze.	XIX	While clearing stuff, a piece of rock fell on his hand.	Wound of left wrist with tendon to middle finger cut.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
7th May ...	94	The Champion Reef Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	6	7	...	1 Manickam ...	35
7th May ...	97	Do ...	10	3	2 Maurimuthoo and	...	35
					Manickam	...	20
						5 Muthuswami ...	30
						Latchmanan ...	35
						Gopal ...	25
						Sanjeevi ... and	25
						Manickam ...	30
9th May ...	95	Do ...	14-30	4½	...	1 R. Chengalaroyan	51
13th May ..	100	Do ...	6-30	7	1 Arokiaswami ...	...	29
15th May ...	101	Do ...	10	3	...	1 Thandavarayan...	23

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Machine cooly ...	Sink 70 feet below the 51st level, Gifford's Shaft.	XIX	While clearing stuff a piece of rock fell on his hand.	Wound of right wrist with extensor tendon cut.
Stuff cooly ...	Rill stope above the 74th level S., South Development Winze.	XI	A series of very heavy rockbursts ...	Body crushed and decomposed. Brought up to surface on 9th May at 7 p.m.
Do ...	Do ...	Do	Do ...	Body highly decomposed and disfigured. Brought up to surface on 12th May at 2-55 p.m.
Packwall cooly ...	Drive 73rd level S., South Development Winze.	Do	Do ...	Wound of left knee joint opened
Do ...	Do ...	Do	Do ...	Contused swelling of ankle with simple fracture of lower end of fibula and wounds, both hands and legs.
Timber cooly ...	Do ...	Do	Do ...	Extensive lacerated wound lower 3rd of left leg and dorsum of right foot.
Packwall cooly ...	Do ...	Do	Do ...	Lacerated wound lower 3rd of right forearm muscles injured and wound dorsum of right hand.
Pipe cooly ...	Do ...	Do	Do ...	Lacerated wounds over left clavicle, heel, contused abrasions of back and wounds of both legs.
Linesman ...	Compound of the Chief Medical Officer's Bunglow, Champion Reef Mine (surface.)	XXIII	While cutting a guy wire, he came in contact with a live wire and fell about 20 feet.	Electric shock with burns of both palms and abrasion dorsum of left foot and fracture of right acetabulum.
Machine maistri (M 14, 015)	Excavation for fan chamber, 40th level, Glen's Secondary Shaft.	XIV	He was caught in the blast before he could retreat to a place of safety after lighting the fuses.	Face disfigured and multiple wounds all over the body.
Machine cooly ...	Rill Stope above the 75th level, S., South Development Winze.	XIX	While clearing stuff, a piece of rock fell on his knee.	Lacerated wound of right knee, joint opened.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
31st May ...	113	The Champion Reef Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	2	3	...	1 Abdul Azeez ...	23
31st May ...	105	Do ...	22	7	...	1 Chadayan ...	45
1st June ...	106	Do ...	5	6	...	1 Dhanapal ...	28
3rd June ...	114	Do ...	18	10	...	1 Abdul Rashid ...	40
8th June ...	111	Do ...	11-30	4½	...	1 Ponnuswami ...	24
12th June ...	116	Do ...	18-30	3½	...	1 Muniswami ...	22
28th June ...	129	Do ...	12	5	...	1 Kannan ...	26
2nd July ...	145	Do ...	10	3	...	1 Balakrishnan ...	25
4th July ...	139	Do ...	14-30	7½	...	1 Dharman ...	21
9th July ...	136	Do ...	13-25	6 5/12	1 Arumugam ...	...	23
15th July ...	149	Do ...	19-30	4½	..	1 Devaraj ..	18
16th July ...	146	Do ...	6	7	...	1 Lakshmanan ..	35

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Tea boy ...	Plat, 51st level, Gifford's Shaft.	XVII	While pulling a bandy from the front, one of the wheels passed over his toe.	Right great toe crushed.
Machine cooly ...	Sink 115 feet below the 55th level, Gifford's Shaft.	XIX	While drilling a hole, a piece of rock fell on his hand.	Lacerated wound of right wrist, extensor tendons cut.
Machine cooly ...	Sink 200 feet below the 51st level, Gifford's Shaft.	XIX	While drilling a hole, a piece of rock fell on his knee.	Lacerated wound of right knee, joint opened.
Tramming maistri	Tramline, bottom of new ore bin, Gifford's Shaft (surface).	XXII	Caught between a bandy and a side of the ore bin.	Contusion of back and contused abrasion of right chest wall.
Machine cooly ...	Stope above the 79th level N., South Development Winze.	XIX	While drilling a hole, a piece of rock fell on his knee.	Wound of right knee, joint opened.
Stuff cooly ...	Drive 75th level N., South Development Winze.	XIX	While clearing stuff, he tripped against a stone and fell.	Wound of right knee, joint opened, wound of left knee (quadriceps, tendon injured) and wounds of both legs.
Stuff maistri (M 15, 031)	Drive, 79th level S., South Development Winze.	XIX	While clearing stuff, a piece of rock fell on his foot.	Lacerated wound dorsum of left foot with compound fracture of 4th metatarsal and extensor tendon cut.
Machine cooly ...	Sink, 200 feet below the 51st level, Gifford's Shaft.	XIX	While filling the bowk, his finger was caught between the edge and a piece of rock.	Lacerated wound of right index finger with compound fracture of proximal phalanx.
Machine cooly ...	Stope above the 74th level S., South Development Winze.	XV	While climbing down by ladder, he slipped and fell.	Compression fracture involving anterior half of 12th dorsal vertebra.
Stuff cooly ...	No. 1 A winze, 76th level S., North Main Winze.	XV	While filling a bandy near a winze he somehow slipped and fell into it.	Multiple wounds all over the body. Died on the way to hospital.
Stuff cooly ...	Drive, 51st level S. Gifford's Shaft.	XVII	Owing to the derailment of a bandy he was pushing, his wrist was injured.	Colles' fracture right.
Machine cooly ...	Drive, 82nd level S., South Development Winze.	XIX	While unrigging the bar, a piece of rock fell on his knee.	Wound of left knee, joint opened.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
17th July ...	147	The Champion Reef Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	14	7	...	1 Iyakannoo ...	20
25th July ...	151	Do	22	7	1 Manickam ...	...	25
31st July ...	154	Do ...	11–30	4½	...	1 Chinnapiah ...	22
19th August ...	163	Do ...	18	3	...	1 Kuppan ...	26
29th August ...	185	Do ...	19-30	4½	...	1 Ponnuswami ...	32
1st September ...	170	Do ...	15–15	6	2 Dasana Boyee	...	55
					and Venkatigadoo.	...	22
30th September...	184	Do ...	21-30	6½	1 Tholasi *alias* Sholay	...	25
7th October ...	186	Do ...	12	5	...	1 Chinnappan ...	40
13th October ...	190	Do ...	6	7	...	1 Madalay ...	20
13th October ...	191	Do ...	12	5	...	1 Sebastian ...	29
16th October ...	192	Do ...	9-30	2½	...	1 Belligadoo ...	37

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Machine cooly ...	Sink of No. 1 winze 150 feet below the 78th level S., North Main Winze.	XIX	While clearing stuff, a piece of rock fell on his knee.	Wound of left knee joint opened.
Stuff cooly ...	Skip road near surface, Glen's Primary Shaft.	VI	While riding upon the edge of the skip, he fell down the shaft.	Fracture of base of skull, back and right leg.
Surface cooly ...	Smoke stack, Old Winder House, Gifford's Shaft (surface).	XXIII	Owing to the collapse of the scaffolding, he fell down a distance of 25 feet.	Fracture of spine at level of 12th dorsal vertebra.
Packwall cooly ...	Rill stope above the 76th level S., South Development Winze.	XI	A burst of quartz.	Wound of lower 3rd of right leg, tendo-achilles completely cut.
Stuff cooly ...	Drive, 77th level N., South Development Winze.	XXVII	While pulling a bandy from the front, a wheel passed over his foot.	Extensive lacerated wounds, dorsum and sole of left foot.
Surface cooly ...	Site for the New Winder House, Gifford's Shaft (surface).	XIII	Collapse of a portion of a side of the excavation for the foundation of the New Winder House.	Suffocation.
Do ...	Do	Do	Do	Do
Packwall cooly...	Rill stope above the 75th level S., South Development Winze.	XI	A rockburst.	Lacerated wounds below right knee, dorsum of right foot, left elbow, left knee and compound fracture of right tibia. Died in hospital at 3-45 P.M. on 3rd October
Machine maistri (M. 14,163).	Rill stope above the 75th level S., South Development Winze.	XIX	While drilling a hole, a piece of rock fell on his knee.	Wound of right knee, joint opened.
Rail cooly ...	Drive, 78th level S., South Development Winze.	XI	A burst of rock.	Lacerated wounds of left shoulder, elbow, middle of forearm, muscles injured with compound fracture of external condyle of humerus and elbow joint opened.
Packwall cooly ...	Stope above the 74th level S., South Development Winze.	XI	A rockburst.	Lacerated wound in front of left ankle joint, tendons and muscles cut, ankle joint opened and fracture of astragalus
Timber cooly ...	Rill stope above the 74th level S., North Main Winze.	XIX	While shifting granite stones, a piece of rock fell on his leg.	Lacerated wound of lower 3rd of right leg, tendo-achilles partly cut.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
16th October ...	193	The Champion Reef Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	10-30	3½	...	1 Muthan ...	30
16th October ...	194	Do ...	11-15	4½	...	1 Chowrinayagam	24
22nd October ...	199	Do ...	9-40	2¾	1 Muniswami ...	...	30
						1 Murugan ...	35
24th October ...	198	Do ...	5	6	...	1 S. Padavattan ...	50
28th October ...	202	Do ...	12-45	5¾	...	1 Doraiswamy ...	24
2nd November ...	203	Do ...	19	4	...	1 Muniswamy ...	30
4th November ...	204	Do ...	22-30	7½	...	1 Appajee ...	26
13th November ...	209	Do ...	22	7	...	1 Mannagatti ...	20
30th November ...	217	Do ...	1	2	1 Muniswami ...	...	50
30th November ...	210	Do ...	5	6	...	1 Munisamy ...	27
4th December ...	213	Do ..	13	6	...	1 Muniswami ...	35

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
per cooly. Handjum	Stope below the 4th level S., old Carmichæl's Shaft.	XIII	Due to the deepening of a socket containing a remnant of the previous charge of explosives.	Peppered wounds of face, chestwall, lacerated wounds of left thigh and leg, wounds and foreign bodies in both eyes with haemorrhage into the anterior chamber of right eye (no vision); left hand crushed.
Stuff cooly ...	Rill stope above the 77th level S., South Development Winze.	XI	A burst of quartz.	Lacerated wound lower 3rd of left leg, tibialis anterior cut.
Timber maistri (M. 13, 094).	Rill stope on the west lode, above 74th level S., North Main Winze.	XI	A very heavy rockburst.	Wounds of scalp, fracture of spine, lacerated wound, dorsum of left foot with compound fracture of fourth toe. Died in hospital on 6th November.
Timber cooly ...	Do	Do	Do	Lacerated wound of left wrist, joint opened, extensor tendons cut, wounds of scalp, face and right shoulder.
Machine cooly ...	Rise above the 27th level S., Tennant's Shaft.	XV	While climbing down by ladder, he slipped and fell about 15 feet.	Fracture of lower ribs with surgical emphysema.
Timber cooly ...	Drive, 70th level S., North Main Winze.	XVII	He was caught between a bandy and a side of the drive.	Fracture middle one-third right radius.
Packwall cooly ...	Drive, 73rd level S., South Development Winze.	XVII	He was caught between a bandy and a side of the level.	Both ears badly lacerated and torn.
Packwall cooly ...	Plat, 74th level South Development Winze.	XIX	While lying in the plat, his foot was struck by a descending cage.	Right foot crushed and amputated.
Stuff cooly ...	Drive, 28th level S., Tennant's Shaft.	XVII	His hand was caught between two bandies.	Colles' fracture left.
Bellman ...	Plat, 74th level, North Main Winze.	XIX	Overcome by heat.	Heat exhaustion.
Stuff cooly ...	Drive, 76th level S., North Main Winze.	XVII	While pushing a bandy from the side, it derailed, and fell on his leg.	Compound fracture of middle third of both bones of left leg.
Machine cooly ...	Rill stope above the 75th level S., South Development Winze.	XI	A burst of quartz ...	Depressed fracture of skull and lacerated wounds of right upper eye lid, nose, right ring finger and contusion of right chestwall.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
15th December ...	215	The Champion Reef Gold Mine, Bowringpet Taluk, Kolar District.—*concld.*	12-45	5¾	...	1 Katherveloo ...	25
31st December ...	223	Do ...	9-30	2½	...	1 Nagadoo ...	38
1st January ...	3	The Ooregum Gold Mine, Bowringpet Taluk, Kolar District.	13-20	6⅓	...	1 P. Chinnaswamy. ..	25
25th January ...	10	Do ...	7	8	...	1 S. Muniswami ...	25
5th February ...	20	Do ...	13	6	...	1 A. Ahmad ...	35
11th February ...	39	Do ...	10-20	3⅓	...	1 P. Chinnapian ...	25
20th February ...	35	Do ...	14-10	7⅙	...	1 K. Ponnuswami.	25
21st Februar ...	34	Do ...	13-21	6 5/6	1 A. Mossa ...	...	28
						1 K. Syed Ali Kutty	35
6th March ...	42	Do ...	9-15	2¼	1 Mohamed ...	...	25
31st March ...	61	Do ...	12-15	5¼	1 M. Kannan ...	...	40
						2 M. Venkataswami and	38

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Machine cooly ...	Stope below the 82nd level, South Section.	XIX	While drilling a hole, a piece of rock fell on his knee.	Wound of left knee, joint opened.
Pipe cooly ...	Drive, 63rd level N., Heathcote Shaft.	XIX	While carrying a pipe he slipped and fell.	Contusion of left arm, wounds of right forearm and hand and colles' fracture neck of humerus.
Timber cooly ...	Drive, 72nd level N., Auxiliary Shaft.	XIX	While taking out lagging poles from a chute, a piece of rock fell on his foot.	Wound dorsum of right foot, superficial flexor tendon of 2nd toe cut and that of 3rd toe injured.
Pipe Fitter ...	Drive, 82nd level S., Auxiliary Shaft.	XIX	While connecting air pipes, a piece of rock fell on his leg.	Wound of lower 3rd of right leg, tendo-achilles partly cut.
Handjumper cooly	Stope below the 72nd level S., Bullen's Incline Shaft.	XIX	While drilling, a piece of rock. fell on his knee.	Wound of right knee, joint opened.
Timber cooly ...	Stope above the 72nd level N., Auxiliary Shaft.	XI	A rockburst	Wounds of scalp, forehead, both eyebrows, left arm, right forearm, dorsum of hand, tip of index finger, lower 3rd of leg, lacerated wounds of lower 3rd of left leg and wound of knee.
Machine cooly ...	Sink, 65 feet below the 85th level, Bullen's Incline Shaft.	XI	A burst of rock	Lacerated wound of lower 3rd of right leg, tendo-achilles completely cut.
Handjumper cooly	No. 12 stope above the 34th level N., Oakley's Incline Shaft.	XI	A rockburst	Compound fracture of skull and multiple injuries to both arms and legs.
Do ...	Do ..	Do	Do	Multiple wounds of scalp, face and front of left clavicle.
Handjumper cooly	No. 2 stope S. below the 78th level S., Bullen's Incline Shaft.	XV	While clearing broken rock he fell into the chute.	Compound fracture of skull with multiple injuries to right leg, right hand and left forearm.
Handjumper cooly	Stope below the 71st level N., Auxiliary Shaft.	XIII	Due to drilling into a socket containing a remnant of the previous charge of explosives.	Lower third of both legs broken, compound fracture of left hand and multiple injuries all over the body.
Handjumper maistri (M. 10,231).	Do ...	Do	Do	Peppered wounds of right forearm, dorsum of hand, face, traumatic conjunctivitis of right eye, wounds of upper third of right leg.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
		Ooregum Gold Mine, Bowringpet Taluk, Kolar District.—*contd.*				V. Kunjayan ...	30
1st April ...	63	Do ...	14	7	...	1 Perumal ...	38
6th April ...	81	Do ...	11	4	...	1 V. Duraiswami ...	18
6th April ...	73	Do ...	22	7	...	1 Murugan ...	33
21st April ...	83	Do ...	10-35	3-7/12	...	1 A. Thangaveloo ...	27
7th May ...	87	Do ...	16-20	1⅓	1 N. Kuttuni Nair	...	45
17th May ...	99	Do ...	18-45	3¾	...	1 V. Kuppuswami	24
2nd June ...	112	Do ...	19-30	4½	...	1 A. Annamalay ...	35
4th June ...	108	Do ...	14	7	...	1 K. Muniswami ...	35
28th June ...	127	Do ...	24	1	...	1 Kannan ...	25
29th June ...	130	Do ...	7-30	½	...	1 O. Doraswamy ...	40
19th July ...	143	Do ...	13	6	...	1 V. Manickam ...	45

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Handjumper cooly	Stope below the 71st level N., Auxiliary Shaft.	XIII	Due to drilling into a socket containing a remnant of previous charge of explosives.	Peppered wounds of face and foreign body in both eyes, contusion of left chest-wall and wounds of left first four toes.
Gang cooly ...	Plat, 42nd level, Bullen's Incline Shaft.	XVIII	While changing ropes, his head was caught between the new reel and its frame.	Wound of scalp with depressed fracture of skull.
Hammerman ...	Blacksmith's Shop, Surface.	XXIII	While turning a steel plate, he sprained his wrist.	Severe cellulitis both dorsal and ventral aspects of left wrist and lower forearm.
Stuff cooly ...	Cross-cut No. 1, 82nd level N., Bullen's Incline Shaft.	XIX	He tripped against a piece of rock and fell.	Potts' fracture left, lacerated wounds with compound fracture of right last two toes.
Timber cooly ...	Bucketway below the 70th level N., Auxiliary Shaft.	XV	While climbing down, he slipped and fell, a distance of about 15 ft.	Wound of scalp, left-eye-brow, both upper extremities, right hip, contused abrasions of back and right chest wall.
Machine mestri (M. 12,024 B. 8,143.)	Cross-cut E., 85th level, Bullen's Incline Shaft.	XI	A rockburst	Multiple injuries to head and body.
Stuff cooly ...	Drive, 55th level N., Oakley's No. 2 Vertical Shaft.	XVII	While lifting a derailed bandy with a lagging pole, it slipped and fell on his shoulder.	Simple fracture of outer third of left clavicle.
Do ...	Drive, 73rd level S., Bullen's Incline Shaft.	XIX	While filling a bandy at a chute, a piece of rock fell on his foot.	Contused wound dorsum of left foot.
Machine cooly ...	No. 8-A winze below the 79th level N., Auxiliary Shaft.	XIX	While clearing stuff, a piece of rock fell on his leg.	Lacerated wound lower 3rd of right leg, tendo-achilles partly cut.
Machine cooly ...	Cross-cut west, 52nd level, Taylor's Main Winze.	XIX	While drilling a hole, a piece of rock fell on his foot.	Wound dorsum of right foot.
Handjumper maistri (M. 5,092 B. 3,259.)	No. 7 stope above the 48th level N., Bullen's Incline Shaft.	XIX	While climbing up by ladder, a piece of rock fell on his foot.	Fractured head of right 2nd metatarsal.
Cage-road cooly	Sink, 160 ft. below the 85th level, Bullen's Incline Shaft.	X	Owing to the derailment of a skip, a piece of rock fell on his arm.	Compound fracture of middle of right humerus.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
30th July ...	152	Ooregum Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	14-45	7¾	...	1 Dhanapal ...	25
31st July ...	158	Do ...	0-30	1½	...	1 Armugam ...	32
18th August ...	160	Do ...	4	5	...	1 A. Kandan ...	25
27th August ...	166	Do ...	20-20	5⅓	...	2 Chinnaswami ...	24
						and	
						Ellappan ...	24
30th August ...	168	Do ...	8-30	1½	...	1 Syed Ali Kutty	18
19th September...	176	Do ...	11	4	1 C. Ponnuswami	...	50
						1 Govindappan ...	40
4th October ...	182	Do ...	11	4	...	1 A. Ponnan ...	38
22nd October ...	197	Do ...	9–38	2-19-30	4 M. Gopala Nair.		35
					C. Muthan ...		35
					N. Padavattan ...		30
					S. Rajoo ...		25

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Machine cooly ...	Cage-road below the 42nd level plat, Oakley's Incline Shaft.	VI	While riding up in the cage his head came in contact with a shaft timber.	Wounds of scalp with concussion of brain.
Do ...	No. 8 stope below the 84th level S., Auxiliary Shaft.	XI	A rockburst	Wounds nape of neck, right knee and contusion of nose.
Unloading cooly	Cage-road above the 70th level, Auxiliary Shaft.	VI	While riding up in a cage with pipes, one of them fell on his arm.	Compound fracture middle of left arm.
Machine cooly ...	No. 6-A stope winze below the 85th level S., Auxiliary Shaft.	XI	A rockburst	Compound fracture of both bones of right leg.
Do ...	Do ...	Do	Do	Compound fracture both bones of lower 3rd of right leg, deep wounds middle of back and muscles cut and lacerated wound of right hand, forearm and scalp.
Handjumper cooly	Stope below the 76th level S., Auxiliary Shaft.	XV	While climbing up by ladder, he slipped and fell down 10 ft.	Wounds of scalp, left leg and simple fracture of middle of left thigh.
Do ...	Stope below the 76th level S., (west-reef) Auxiliary Shaft.	XIII	Through drilling into a socket containing a remnant of the previous charge of explosives.	Penetrating wounds of back with injuries to left hand, right ankle, and right shoulder.
Do ...	Do ...	Do	Do ...	Left eye burst, wound and foreign bodies in right eye and peppered wounds of face, left forearm, leg and extensive lacerated wound of right hand.
Cage road cooly ...	Quartz chute above the 71st level plat, Bullen's Incline Shaft.	VIII	While repairing a chute, a few planks gave way and he fell about 16 ft.	Facture of Spine.
Machine cooly ...	Drive 64th level S., Auxiliary Shaft.	XI	A series of very heavy rockbursts ...	Multiple injuries all over the body.
Stuff cooly ...	Do	Do	Do	Do
Timber cooly ...	Drive 66th level N., Auxiliary Shaft.	Do	Do	Do
Do ...	Do	Do	Do	Do

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
)ate of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed *(All males unless otherwise stated)*	Names and Number of Persons injured *(All males unless otherwise stated)*	Reputed Age
		Ooregum Gold Mine, Bowringpet Taluk, Kolar District—*concld.*				4 M. Bangaroo ...	28
						T. Rajoo ...	35
						A. Vardah ...	30
						A. Perumal ...	28
th November...	205	Do	13-50	6 5/6	...	1 V. Perumal ...	35
th November ...	207	Do	14	7	...	1 A. Kannan ...	30
)th December ...	221	Do	12	5	...	1 Munsiammal (Female).	45
)th December ...	220	Do	12	5	1 K. Kolanday ...	...	45
						2 Alavee ...	34
						and	
						Srinivasan ...	24

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Stuff cooly ...	Drive, 58th level S., Oakley's No.2 Vertical Shaft.	XI	A series of very heavy rockbursts ...	Lacerated wound of right knee, joint opened, quadriceps femoris cut and lacerated wound of right index and last finger, extensor tendons cut.
Do ...	Drive, 64th level S., Auxiliary Shaft.	Do	Do	Compound fracture of both bones and wound end of left leg, lacerated wound of middle of right thigh and hip.
Timber cooly ...	Drive, 57th level N., Bullen's Incline Shaft.	Do	Do	Lacerated wound lower 3rd of left leg, tendo achilles partly cut and contused swelling of lower part of back.
Do ...	Drive, 66th level N., Auxiliary Shaft.	Do	Do	Contusion lower part of back and wound eyebrow and left leg, with fracture fourth lumbar vertebra.
Sawyer cooly ...	Timber yard near Carpenter's Shop. (surface).	XXIII	While rolling a log in the timber yard, another fell on his leg.	Compound fracture of both bones of upper 3rd of left leg.
Timber maistri (M. 14,406).	Rise for head gear, No. 3 winze, 85th level N., -Auxiliary Shaft.	XV	While climbing down by ladder he slipped and fell a distance of 21 feet.	Fracture of right rib with surgical emphysema.
Coal cooly ...	Coal yard near the General Stores (surface).	XXIII	While unloading coal from a wagon, a chip flew into her eye.	Corneal ulcer of right eye (central) with diminished vision.
Handjumper cooly.	Stope below the 70th level S., Bullen's Incline Shaft.	XIII	Through drilling into an old hole containing a portion of a previous charge of explosives.	Right hand crushed below elbow, both the forelegs crushed above ankle. Right eye burst, peppered wounds of face and multiple wounds all over body.
Do ...	Do	Do	Do	Peppered wounds of both fore-arms left side of chest wall and wound of left eye with hæmorrhage into the anterior chamber.
Do ..	Do	Do	Do	Peppered wounds all over the body and wounds and foreign bodies in both eyes.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
8th January ...	4	Nundydroog Gold Mine, Bowringpet Taluk, Kolar District.	7-45	¾	...	1 C. Manickam ...	45
28th January ...	15	Do ...	9-30	2½	...	1 K. Varaden ...	35
1st February ...	30	Do ...	20-30	5½	...	1 M. Poongavanam	28
2nd February ...	19	Do ...	3-30	4½	...	1 M. Kandan ..	20
6th February ...	22	Do ...	11	4	1 W Murugan ...	...	30
						1 V. Govindan ...	25
14th February ...	31	Do ...	20-30	5½	...	1 K. Chinnappah...	29
15th February ...	45	Do ...	15-30	½	...	1 S. Muniswami ...	20
15th February ...	46	Do ...	16-30	3½	...	1 Madurai Modaliar.	50
3rd March ...	38	Do ...	13-30	6½	...	1 S. Yellappan ...	38
10th March ...	48	Do ...	13-40	6⅔	...	1 K. Chinna Ramaswamy.	30
20th March ...	52	Do ...	11	4	...	1 P. Chowdappa ...	25

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Shift Boss. (M. 9,997 B. 6,981).	Tennants' shaft (collar), Balaghat Section.	XIX	He was struck by a hammer which missed the bar he was holding, and fell on his arm.	Simple fracture middle third of right radius.
Machineman ...	Drive, 64th level S., No. 3 Auxiliary Shaft.	XIX	While clearing stuff, a piece of rock fell on his knee.	Wound of right knee, joint opened.
Concreting cooly...	Rill stope above the 55th level N., No. 1 Auxiliary Shaft. ...	XVIII	His fingers were caught between the scraper rope and the wheel.	Left middle finger crushed and amputated at the metacarpo phalangeal joint, lacerated wounds of left index, ring and little fingers and right ring finger and contusion lower 3rd of right arm.
Stuff cooly ...	Stope-below the 55th level S., No. 2 Auxiliary Shaft.	XI	A burst of quartz	Wound of right knee, joint opened.
Timber cooly ...	Plat, 51st level, No. 2 Auxiliary Shaft.	VIII	While attempting to board the cage in a hurry he fell down the shaft.	Body dismembered.
Stuff cooly ...	Do ...	Do	Do ...	Extensive lacerated wound dorsum of right foot, heel and outer ankle.
Machine cooly ...	Sink 80 feet below the 66th level, No. 3 Auxiliary Shaft.	XIX	While lifting a piece of rock it broke and a portion fell on his leg.	Wound lower 3rd of right leg, tendo-achilles completely cut.
Oil boy ...	Picking Floor (surface).	XX	While greasing the pinion wheel of a trommel in motion, his fingers were caught in the pinion.	Right last three fingers crushed and amputated.
Blacksmith ...	Fitting Shop (surface).	XXIII	While forging a piece of steel a hot scale flew into his eye.	One day old corneal abrasion of left eye with cataract in both eyes.
Machine maistri (M. 11,656—B. 7,936).	Drive, 65th level S., No. 3 Auxiliary Shaft.	XIX	While drilling a hole, a piece of rock fell on his knee.	Lacerated wound of right knee, joint opened.
Handjumper cooly.	Stope below the 52nd level N., No. 1 Auxiliary Shaft.	XI	A rockburst	Wounds of both knees, left knee joint opened, lacerated wound of left forearm, wrist and head.
Timber cooly ...	Drive, 60th Level N., No. 1 Auxiliary Shaft.	XI	A burst of rock	Contused wounds of right hip, wounds of face (right), inner side of right foot and left elbow.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
24th March ...	57	The Nundydroog Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	5	6	...	1 T. Muniswami ...	40
24th March ...	58	Do ...	18	3	...	1 K. Varadan ...	45
29th March ...	59	Do ...	9-30	2½	...	1 K. Murugan ...	32
31st March ...	64	Do ...	13-45	6¾	...	1 P. Dasappah ..	25
31st March ...	62	Do ...	21-5	6 1/12	...	1 P. Rajagopal ...	22
1st April ...	65	Do ...	12-30	5½	...	1 G. Guiseppe ...	38
5th April ...	66	Do ...	6-35	...	...	1 C. Narayanan Nair.	28
5th April ...	67	Do ...	8-40	1½	1 K. V. Moideen ...	...	48
						1 T. Kunjaimoo ...	28
6th April ...	69	Do ...	0-20	9⅓	...	1 C. H. Millington	28
9th April ...	71	Do ...	21-30	6½	...	1 B. Murugan ...	22
10th April ...	72	Do ...	23	..	...	1 C. Varadaraj ...	32
16th April ...	74	Do ...	13-45	6¾	...	1 B. Maduraimuthu	40
20th April ...	77	Do ...	18-15	3¼	...	1 S. Murugase ...	36

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Machine cooly ...	Drive, 64th level S., No. 2 Auxiliary Shaft.	XIX	Some pieces of loose rock fell on his leg.	Lacerated wound of left knee, joint opened with Potts' fracture.
Machine cooly ...	Drive, 64th level S., No. 2 Auxiliary Shaft.	XIX	While drilling a hole some slush flew into his eye.	Corneal ulcer of right eye.
Stuff maistri (M. 14,528).	Crosscut W., 66th level, No. 4 Auxiliary Shaft.	XI	A burst of rock	Fracture of spine (lumbar region), wounds of right index and middle fingers.
Pipe fitter cooly.	Drive, 53rd level N., No. 1 Auxiliary Shaft.	XIX	A lagging pole was dislodged on his foot.	Extensive lacerated wound sole of left foot with compound fracture of last metatarsal.
Machine cooly .	Drive, 64th level S., No. 2 Auxiliary Shaft.	XI	A burst of rock	Wound of scalp, fracture of left clavicle.
Foreman ...	Sink, 320 feet below the 66th level, No. 4 Auxiliary Shaft.	VIII	The stage on which he was standing collapsed causing him to fall a distance of 10 feet.	Potts' fracture right.
Furnace man ...	Zinc lathe room, Slimes Plant (Surface).	XX	While cleaning a lathe, his arm was caught between its base and the pulley.	Compound fracture of middle of both bones of right forearm.
Handjumper cooly.	S. 19 stope below the 54th level S., No. 3 Auxiliary Shaft.	XIII	Through drilling into a socket containing a remnant of the previous charge of explosives.	Multiple injuries to head and body.
Do ...	Do — ...	Do	Do ...	Wounds and foreign bodies all over body, both eyes burst, right knee joint opened and compound fracture of right little finger.
Assistant Foreman (M. 14, 542).	N. 14 stope above the 57th level N., No. 1 Auxiliary Shaft.	XI	A rockburst	Laceration of left forearm, contusion of right arm and back, injury to 5th lumbar vertebra.
Machine cooly ...	Drive, 63rd level N., No. 1 Auxiliary Shaft.	XIX	While cleaning a hole, a piece of rock fell on his knee.	Wound of right knee, joint opened.
Machine cooly ...	Ladderway above the 64th level, No. 1 Auxiliary Shaft.	XIX	While climbing down by ladder, he slipped and fell a distance of 10 feet.	Simple fracture of lower 3rd of right arm.
Gang cooly ...	Tennant's Shaft (surface.)	XXIII	While lifting a timber, it fell on his leg.	Potts' fracture left.
Machine cooly ...	Plat, 67th level, No. 3 Auxiliary Shaft.	XIX	While clearing stuff a piece of rock fell on his knee.	Wounds of right knee, joint opened and wound of great toe.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
25th April ...	78	The Nundydroog Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	13-15	7	1 M. Murugan ...	...	26
1st May ...	85	Do ...	21	6	...	1 P. Annamaly ...	25
5th May ...	96	Do ...	13	6	...	1 P. Kesavan ...	28
6th May ...	88	Do ...	14	7	...	1 K. Aruldoss ...	15
13th May ...	98	Do ...	20	5	...	1 K. Dorasami ...	23
22nd May ...	102	Do ...	6-45	7¾	1 S. Sanjeevi ...	...	25
27th May ...	103	Do ...	11-30	4½	...	2 K. Marappan ...	22
						and	
						T. Vellai ...	36
31st May ...	107	Do ...	9-30	2½	...	1 S. Muniswami ...	30
1st June ...	109	Do ...	14	1	...	1 M. Nadesa Mudaliar.	40
2nd June ...	110	Do ...	21	6	...	1 V. Perumall ...	30
3rd June ...	121	Do ...	16-15	1¼	...	1 M. Narasan *alias* Narasimhan.	35

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Stuff cooly ...	S. 13 Winze, 64th level N., No. 3 Auxiliary Shaft.	XV	He somehow slipped and fell down a winze—a distance of about 24 feet.	Lacerated wound of scalp and simple fracture of right femur.
Machine cooly ...	N. 21 stope above the 54th level N., No. 1 Auxiliary Shaft.	XIX	While drilling a hole, some slush flew into his eye.	Corneal ulcer of right eye (central) with diminished vision.
Timber cooly ...	Winze below the 42nd level N., Kennedy's Main Winze.	XIX	While fixing a timber, some pieces of rock fell on his arm.	Lacerated wounds of left forearm, muscles cut.
Cleaner ...	Tube Mill House (surface).	XX	His arm was caught in a revolving shafting.	Greenstick fractures of both bones of lower 3rd of left forearm.
Machine cooly ...	Sink of S. 8 winze below the 63rd level, N., No. 3 Auxiliary Shaft.	XIX	While clearing stuff, a piece of rock fell on his knee.	Wound of left knee, joint opened.
Stuff cooly ...	Cage road above 64th level plat, No. 3 Auxiliary Shaft.	VI	While riding up in the cage, he fell down the shaft.	Multiple injuries to head and body.
Handjumper cooly	N. 27 stope below the 44th level N., Oriental Section.	XIII	Through intersecting a socket containing a small quantity of an unexploded charge of blasting gelatine.	Foreign bodies in both eyes with no vision in right eye. Peppered wounds of face, chest wall and both extremities.
Do ...	Do ...	Do	Do ...	Foreign bodies in right eye, peppered wounds of face, all over body, lacerated wounds lower third of right forearm, flexor muscle injured, palm of hand and right little finger crushed and amputated at the proximal joint.
Timber cooly ...	N. 22 Rill stope above the 53rd level N., No. 1 Auxiliary Shaft.	XIX	While walking down the rill, a piece of rock fell on his leg.	Wound over right tendo-achilles, tendon partly cut.
Moulder ...	Moulding shop (Surface).	XXIII	While straightening a wire, it broke off and struck his eye.	Traumatic cataract of right eye (no vision).
Machine cooly ...	N. 26 stope above the 54th level N., No. 1 Auxiliary Shaft.	XIX	While drilling with a telescopic machine, the feed pole slipped and struck his foot.	Lacerated wound dorsum of left foot, tendon slightly injured.
Stuff maistri (M. 10,789).	Chute, 55th level N., No. 2 Auxiliary Shaft.	XIX	While running stuff from a chute a piece of rock rolled down and struck him.	Contused wound right side of face. "X-Ray" examination revealed "fracture-base of skull."

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed *(All males unless otherwise stated)*	Names and Number of Persons injured *(All males unless otherwise stated)*	Reputed Age
12th June ..	123	The Nundydroog Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	6	7	...	1 Masilamony ...	24
15th June ...	117	Do	13	6	...	1 S. Kuppu Raj ...	22
16th June ...	115	Do ...	12–15	5¼	...	1 K. Mohamed ...	40
19th June ...	148	Do ...	9–15	2¼	...	1 M. Govindan ...	20
22nd June ...	119	Do ...	11–5	4	...	1 S. Chinnaswami	22
23rd June ..	126	Do ...	8–30	1½	...	1 C. Narayanan Nair	52
24th June ...	124	Do ...	9	2	...	1 A. Ponnan ...	24
25th June ...	122	Do ...	3–30	4½	..	1 K. Ramaswami...	40
1st July ...	128	Do ...	13–30	6½	..	1 C. Moideenkutty	35
9th July ..	134	Do ...	20	5	1 P. Veloo ...	...	24
12th July ...	137	Do ...	11	4	1 M. Armugam ...	...	30
						1. T. Raghavan ...	45
16th July ...	141	Do ...	5–40	6	...	1. V. Thiruvengadam.	37

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Hoisting cooly ...	Tramline, Picking Floor (surface).	XXII	While lifting a bandy he slipped and fell.	Wound of chin, abrasions of right forearm, leg and contusion of scrotum.
Stuff cooly ...	Drive, 57th level S., No. 3 Auxiliary Shaft.	XI	A burst of quartz	Wound of left knee, joint opened.
Handjumper cooly	Stope below the 52nd level S., No. 3 Auxiliary Shaft.	XI	A rockburst	Wound below right knee, pattellar tendon and bone cut.
Stuff cooly ...	Drive, 57th level S., No. 1 Auxiliary Shaft.	XIX	While clearing stuff, a piece of rock rolled down from the top of the pile and struck his leg.	Lacerated wounds of left leg with tendo-achilles partly injured.
Timber cooly ...	S. 24 stope below the 58th level S., No. 3 Auxiliary Shaft.	XIX	While breaking a granite stone, a chip flew into his eye.	Penetrating wound of right eye.
Handjumper cooly	S. 17 stope below the 60th level N., No. 3 Auxiliary Shaft.	XIX	While cleaning down stuff, a piece of rock fell on his leg.	Lacerated wounds lower 3rd of left leg, tendo-achilles partly cut.
Stuff cooly ...	S. 23 stope below the 60th level S., No. 3 Auxiliary Shaft.	XIX	While cleaning down stuff, a piece of rock fell on his knee.	Lacerated wound of right knee, joint opened.
Machine maistri (M. 14,446-B 9, 218).	Drive, 58th level S., No. 3 Auxiliary Shaft.	XIX	While breaking a large piece of rock, a chip flew into his eye.	Penetrating wound of right eye with prolapse of iris.
Handjumper cooly.	S. 23 stope below the 61st level S., No. 3 Auxiliary Shaft.	XI	A burst of quartz ...	Lacerated wound dorsum of right hand, left knee joint opened and contused abrasion of back, right side of face and forearm.
Stuff cooly	N. 24 winze, 55th level N., No. 1 Auxiliary Shaft.	XV	While walking along the level, without a light, he stepped into an open winze.	Multiple injuries to head and both legs.
Timber cooly ..	Cage road above the 42nd level, Tennant's Main Winze.	X	While riding up in the cage, they were struck by a timber falling down the shaft.	Deep extensive lacerated wound of left shoulder (shoulder almost severed) and wound of right cheek.
Timber Maistri (M. 9925—B. 6950).	Do ...	...	Do ...	Fracture of lumbar spine.
Concreting cooly.	N. 26 stope above the 55th level N., No. 1 Auxiliary Shaft.	XV	While climbing down by ladder, he slipped and fell 15 feet.	Compound depressed fracture of skull, wounds of face, left forearm and both legs.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
16th July ...	142	The Nundydroog Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	9-15	2¼	...	2 C. Appadorai ... and Y. Chengan ...	37 25
18th July ...	144	Do ...	17-45	2¾	...	1 A. Abboy ...	38
20thAugust ...	161	Do ...	12	5	...	1 S. Kannan ...	26
20th August ...	162	Do ...	15-30	½	1. K. Mohamed Kutty	...	52
21st August ...	164	Do ...	10-30	3½	...	1 Ranganathan ...	28
24th August ...	169	Do ...	11	4	...	1 Thangavelu ...	50
28thAugust ...	167	Do ...	2-45	3¾	...	1 K. Kathirveloo ...	36
30th August ...	173	Do ...	7-50	1-	...	1 A. Vellai ...	20
9th September	174	Do ...	2	3	...	1 N. Veloo ..	24

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Machine Maistri (M. 12,967—B. 8,613).	Sink, 450 feet below the 66th level, No. 4 Auxiliary Shaft.	XI	A rockburst ...	Simple fracture middle of left arm, wound dorsum of left index finger and leg.
Machine cooly ...	Do ...	Do	Do ...	Wound of scalp, face, left wrist, extensor tendon cut.
Machine cooly ...	Stope above the 59th level N., No. 1 Auxiliary Shaft.	XIX	While drilling, the machine fell on his hand.	Colles' fracture right.
Timber cooly ...	S. 23 stope above the 61st level S., No. 3 Auxiliary Shaft.	XI	A burst of quartz ...	Wound of left knee, joint opened and lacerated wound of left leg extensor tendon cut in front of the ankle joint.
Blaster (M. 12,251—B. 8,236).	Stope below the 47th level S., Kennedy's Main Winze.	XV	While climbing from the stope to the level, he slipped and fell down the orepass.	Compound comminuted fracture upper end of right tibia and multiple wounds all over the body. Died in hospital the same day.
Machine cooly ...	S. 21 winze below the 59th level S., No. 3 Auxiliary Shaft.	XIII	Through deepening a socket containing a remnant of the previous charge of explosives.	Foreign bodies in both eyes with penetrating wound of right eye, hæmorrhage into the interior chamber wounds of face, penetrating wound of right cheek, peppered wounds of both upper extremities and chest wall.
Machine maistri (M. 8,153—B. 5866).	Stope above the 54th level N., No. 2 Auxiliary Shaft.	XV	The stage on which he was standing gave way and he fell about 10 feet.	Wounds of scalp, left index and middle fingers, contusion of right hip and contused abrasion of right knee with traumatic synovitis.
Machine cooly ...	Crosscut E., from the 69th level plat, No. 4 Auxiliary Shaft.	XI	A burst of rock ...	Wound lower 3rd of left leg, tendo-achilles cut.
Handjumper cooly	S. 7 stope below the 60th level S., No. 2 Auxiliary Shaft.	XV	While clearing stuff, a piece of granite fell on his back.	Fracture of first lumbar vertebra.
Stuff cooly ...	S. 23 stope below the 60th level S., No. 3 Auxiliary Shaft.	XIX	While clearing stuff, a stone fell on his knee.	Wound of left knee, joint opened.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
14th September...	175	The Nundydroog Gold Mine, Bowringpet Taluk, Kolar District—*contd.*	19	4	...	1 K. Ponnuswami	48
22nd September...	177	Do ...	11-10	4	1 K. Venkatappa...	...	40
28th September...	178	Do ...	9-20	2⅔	1 K. Muniswami...	...	44
3rd October ...	181	Do ...	8-45	1¾	1 P. Kuppuswamy	...	26
18th October ...	195	Do ...	13-30	6½	1 Kunjukuttan Eluthachan.	...	43
						2 Kunju Nair ...	25
						and	
						C. Ramaswami...	26
21st October ...	196	Do ...	11-45	4¾	...	1 K. Mottaigone ...	30
28th October ...	201	Do ...	9	2	...	1 M. Kunju Nair.	30
6th November ...	211	Do ...	4	5	...	1 S. Chinnappan ...	19

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Continued.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Handjumper cooly	N. 3 stope below the 650 ft. level N., Nine Reefs.	XIX	While drilling a hole some slush flew into his eye.	Big corneal ulcer of left eye, with hypopion. No vision.
Timber cooly ...	S. 27 stope above the 51st level S., No. 3 Auxiliary Shaft.	XI	A rockburst ...	Fracture of spine and lacerated wound upper part of back, right arm, dorsum of left hand, right leg and abrasion of forehead. Died in hospital the same day.
Stuff maistri M. 13,668).	N. 24 winze below the 64th level N., No. 1 Auxiliary Shaft.	XV	He fell down the bucket road. ...	Simple fracture of left arm. Fracture of two or three ribs. Fracture middle of spine. Compound fracture of both bones of right leg. Multiple wounds all over the body with probable internal injuries. Died on arrival at the hospital.
Machine cooly ...	Plat of S. 16 winze 66th level S., No. 3 Auxiliary Shaft.	XI	A rockburst ...	Wounds of scalp with fracture base of skull.
Handjumper cooly	S. 8 stope below the 54th level S., No. 2 Auxiliary Shaft.	XI	A rockburst ...	Left foot and leg crushed and amputated below knee. Patellar tendon cut, wound of upper part of back, right elbow and face. Died in hospital the same day.
Do ...	Do ...	Do	Do ...	Simple fracture lower third of left thigh and lacerated wound of left arm.
Do ..	Do ...	Do	Do ...	Wound lower third of left leg, tendo-achilles cut.
Timber cooly ...	N. 23 stope below the 59th level N., No. 1 Auxiliary Shaft.	XV	Owing to the collapse of the stage on which he was standing, he fell down a distance of 6 feet.	Simple fracture both bones middle 3rd of left leg.
Handjumper cooly.	S. 17 stope below the 60th level S., No. 2 Auxiliary Shaft.	XIX	While drilling a hole, some slush fell into his eye.	Corneal ulcer right eye.
Bull driver ...	Tramline, Picking Floor Yard (surface).	XXII	Owing to the derailment of the bandy, his leg was caught beneath its frame.	Fracture of right fibula.

RECORD OF FATAL

AT MINES WORKING IN THE STATE

1	2	3	4	5	6	7	8
Date of Accident	Registered Number of Accident	Name and Situation of Mine	Time of Accident (counting hours from midnight)	Number of hours worked before Accident	Names and Number of Persons killed (*All males unless otherwise stated*)	Names and Number of Persons injured (*All males unless otherwise stated*)	Reputed Age
4th December ...	214	The Nundydroog Gold Mine, Bowringpet Taluk, Kolar District. —*contd.*	7-55	¾	2 M. Krishtan ...	...	25
					and		
					M. Chamy Kutty	...	23
						1 P. Chinna Raman.	40
20th December ...	216	Do ...	11	4	...	2 P. Raman ...	28
						and	
						Govindan Nair...	29
23rd December ...	218	Do ...	10-30	3½	1 T. Vellai ...	...	40
31st December ...	222	Do ...	16	8	...	1 K. Chengada Goundan.	54
14th January ...	21	Keshapur Mine, Holalkere Taluk, Chitaldrug District.	14-30	5	...	1 H. Thimma ...	40
19th February ...	49	Government Chrome Mines, Byrapur, Channarayapatna Taluk, Hassan District.	15	5	1 Chicki (Female)	...	35
20th August ...	165	The Indian Mines Development Syndicate, Ltd., Manighatta Block, Kolar Taluk, Kolar District.	15-30	6	1 G. Venkatappa.	...	25
24th September.	187	Do ...	15	7	...	1 S. Venkataramiah	54
1st October ...	183	Mysore Iron Mines, Kemmangundi, Tarikere Taluk, Kadur District.	10	2	1 Bora ...	...	25

AND SERIOUS ACCIDENTS

OF MYSORE DURING THE YEAR 1937.—*Concluded.* Table 13.

9	10	11	12	13
Occupation	Place of Accident	Class of Accident in terms of Table 7	Cause of Accident	Nature of Injury
Handjumper cooly	Drive, 4,600 ft. level N., Oriental Section.	XI	A rockburst	Multiple wounds of face and left side of back left leg fractured above the knee with thigh muscles cut.
Do ..	Do ...	Do	Do	Wound of right hand and right leg crushed.
Do ...	Do ...	Do	Do	Lacerated wound of right knee, patellar tendon cut, wounds of left knee, leg, both hands and contusion of lower part of back.
Handjumper cooly	S. 24 stope below the 54th level S., No. 3 Auxiliary Shaft.	XIII	Through drilling into a socket containing a remnant of the previous charge of explosives.	Wounds all over the body, foreign body right eye and left eye burst.
Do ...	Do ...	Do	Do	Wounds and foreign body both eyes, peppered wound of face, chest, neck and both arms.
Stuff cooly ...	N. 21 winze below the 61st level N., No. 1 Auxiliary Shaft.	XV	While clearing the spillage after tipping a bandy into a chute, he slipped and fell into it.	Multiple injuries to head and body.
Handjumper maistri (M. 5753).	S. 16 stope below the 62nd level S., No. 3 Auxiliary Shaft.—	XIX	While taking down loose a small chip of rock flew into his eye.	One day old wound of right cornea (central) with diminished vision.
Stuff cooly ...	No. 20 Pit (surface)...	XXIII	Fall of ground	Spinal injury.
Do ...	'A' Pit, SouthBank.	XXIII	While walking up an incline, she overbalanced and fell a distance of 30 feet.	Probable fracture of base of skull.
Trench cooly ...	Trench H, 129. F. Area.	XXIII	Fall of ground	Suffocation. Body recovered on 27th August.
Road-making cooly.	Ethuroor Road, Manighatta prospecting Block.	XXIII	While pushing a wheel of a lorry, he slipped and fell.	Colles' fracture left.
Loading cooly ...	Bunker platform (surface).—	XXIII	While pushing a bandy, he slipped and fell, a distance of 15 feet.	Spinal injury. Died in hospital on 4th October.